Atty. Ref.: 9694-000003/NP

1/21

BEST AVAILABLE COPY

Fig. 1




Fig. 2







Fig. 3








4/21


Fig.5

















Fig ZOA



12/21

Fig, 20B






Fig. 20C



14/21

Fig. 20D



10/502457

15/21

Fig. 20E





Fig. 21



To/From SDL
Control Signals Storage Element interface

Fig. 22




Fig. 23






Fig. 24



20/21

Fig. 25




Title: DATA STORAGE SYSTEM
- Inventors: Kirk Donald WILSON, et al.

Atty. Ref.: 9694-000003/NP

21/21

Fig. 26



10/502/57

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

OTHER:

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.